



Photo 1: General view of the house and barn, from the south-west



Photo 2: House and barn, from the south-west



Photo 3: The house, from the south



Photo 4: South gable of the house



Photo 5: House and south end of barn, from the west



Photo 6: House and barn, from the south-east





Photo 7: Rear elevation of house and barn




Photo 8: Rear elevation of the house





Photo 9: The barn, from the south-west




Photo 10: Front elevation of the barn, from the north-west



Photo 11: Detail of cart entrance to barn, and window over



Photo 12: Detail of dated window in front elevation of barn



Photo 13: Detail of doorway at north end of barn




Photo 14: Rear elevation of the barn





Photo 15: Barn and house, from the north




Photo 16: North gable of the barn




Photo 17: Interior of barn, from the north-west



Photo 18: View of underside of barn roof, from the west



Photo 19: North-west addition, from the south



Photo 20: Detail of blocked doorway into addition, from the south-west





Photo 21: East side of north-west addition




Photo 22: North side of north-west addition