



Photo 1: General view of the Hall, from the south-west




Photo 2: General view of the Hall, from the south



Photo 3: The east wing, from the south-east



Photo 4: The east wing and main range, from the south



Photo 5: The east part of the Hall, and the east wing, from the south-west



Photo 6: The front elevation of the main range, from the east wing



Photo 7: Detail of stone plinth at foot of east wing, front elevation



Photo 8: South elevation of the east wing



Photo 9: East wing: lower part of front elevation



Photo 10: East wing: middle part of front elevation



Photo 11: Detail of timber framing on front elevation of east wing



Photo 12: Detail of carved timber frieze on front elevation of east wing



Photo 13: East wing: upper part of front elevation: the projecting gable is mostly of modern timber



Photo 14: Wind brace at south-east corner, with modern timbers beyond (nothing of the original south truss appears to survive)



Photo 16: East wing: the west elevation, above hedge and lean-to



Photo 15: East wing: south part of east elevation and chimney stack. from the south-east





Photo 17: Ground floor room of no 247, from the south-east



Photo 18: Detail of chamfer and stop, to west end of cross beam over ground floor



Photo 19: Collar and ridge of truss over middle of no.247, from the north



Photo 20: Wind braces on east side of middle truss



Photo 21: Detail of stone plinth and remnant of sill beam (on which the scale rests), at north-west corner of ground floor



Photo 22: Detail of joint of first floor beam with post, at north-east corner of ground floor



Photo 24: First floor: north-west wall post and tie beam with brace pegs, to right



Photo 23: First floor: north-east wall post and brace, with stud and 19th century window to right