Devon County Council Historic Environment Record

Civil Parish: Membury		tional Grid Reference 3142 104424 (ST)	Number: (Leave blank)
Subject: Challenger Farm, Membury, Axminster, Devon Plan/Photo attached			Plan/Photo attached? Y
Planning Application no: 15/1768/FUL		Recipient museum: Royal Albert Memorial Museum	
OASIS ID: contexto1-295448		Museum Accession no: RAMM: 17/53	
Contractor's reference code: C1/AMR/17/CMD		Dates fieldwork undertaken: 08/09/17 and 10/01/19	
Description of works. Context One Heritage and Archaeology (C1) carried out an archaeological investigation as a condition of granting planning permission for the construction of an agricultural dwelling at Challenger Farm (Figure 1). In the event, the dwelling was constructed up to ground floor level without monitoring and recording having taken place. Following consultation with Stephen Reed, Senior Historic Environment Officer, DCC, it was agreed that three small compensatory trenches would be cited in areas undisturbed by the groundworks. The trenches measured <i>c</i> . 5m long x 1.6m wide and were excavated archaeologically using a 360-degree tracked machine equipped with a toothless (grading) bucket.			
The topsoil in all three trenches was identical: 0 – 0.20m Topsoil (100) - Brown (7.5 YR 4/4) firm sandy silty clay with frequent angular chert fragments <0.20m			
The remaining stratigraphic sequence consisted of:			
Trench 1 (Plate 1) 0.20-0.60m Subsoil (101) - Strong brown (7.5 5/6) firm sandy silty clay with moderate angular chert fragments <0.20m			
0.60m – >0.80m Natural (102) - Strong brown (7.5 5/8) firm sandy silty clay with frequent angular gravel <0.05m			
Trench 2 (Plate 2) 0.20-0.60m Subsoil (201) - Light brown (7.5 6/3) firm sandy silty clay with moderate angular chert fragments <0.20m			
0.60m – >0.65m Natural (202) - Reddish brown (7.5 6/8) firm sandy silty clay with frequent angular gravel <0.06m and occasional angular chert fragments <0.30m			
Trench 3 (Plate 3) 0.20-0.60m Subsoil (101) - Strong brown (7.5 5/6) firm sandy silty clay with moderate angular chert fragments <0.20m			
0.60m – >0.65m Natural (102) - Strong brown (7.5 5/8) firm sandy silty clay with frequent angular gravel <0.05m			
No archaeological features or deposits were observed and no artefacts or ecofacts were seen or collected.			
A plan as well as any other relevant drawings must be attached showing the location and extent of site, areas investigated and features exposed.			
Recorder: Tara Fairclough Context One Heritage and Archaeology.			Date sent to HER 28/01/19




Figure 1. Site setting with trench and profile locations





Plate 1. Trench 1 (facing N; 2 x 1m scale)

Plate 2. Trench 2 (facing W; 2 x 1m scale)



Plate 2. Trench 3 (facing W; 2 x 1m scale)

Any plans or photographs embedded within or attached to this form remain the copyright © of the recorder, and must not be reproduced in any publication without the explicit consent of the copyright holder.

Please email the completed form to: archaeol@devon.gov.uk or post to Historic Environment Service, Devon County Council, Lucombe House, County Hall, Exeter EX2 4QD. Information recorded on this form will be added to the Historic Environment Record, and be made available to researchers.