WEST MILL, ASKRIGG, NORTH YORKSHIRE

ARCHAEOLOGICAL AND ARCHITECTURAL SURVEY

VOLUME 2: FIGURES AND PLATES



Ed Dennison Archaeological Services Ltd 18 Springdale Way Beverley East Yorkshire HU17 8NU

WEST MILL, ASKRIGG, NORTH YORKSHIRE

ARCHAEOLOGICAL AND ARCHITECTURAL SURVEY

VOLUME 2: FIGURES AND PLATES

Report no: 2010/388.R01

Version: Final

Date: September 2012

Authors: Shaun Richardson & Ed Dennison

Ed Dennison Archaeological Services Ltd 18 Springdale Way Beverley On behalf of

East Yorkshire HU17 8NU Professor D Blake

West Mill Askrigg Leyburn

North Yorkshire DL8 3HR

ARCHAEOLOGICAL AND ARCHITECTURAL SURVEY, WEST MILL, ASKRIGG, NORTH YORKSHIRE

CONTENTS OF VOLUME 2


List of Figures

- 1 General location.
- 2 Areas of survey.
- 3 Turner's 1816 sketch.
- 4 1839 tithe map.
- 5 Ordnance Survey 1856 map.
- 6 Ordnance Survey 1856 map (detail).
- 7 Ordnance Survey 1893 map (detail).
- 8 Plan with 1908 conveyance.
- 9 Mill Gill power system.
- 10 Ordnance Survey 1912 map (detail).
- 11 1913 conveyance.
- 12 Plan with 1913 conveyance.
- 13 Receipts and invoices 1917-1922.
- 14 Account of work 1943.
- 15 Receipts and invoices 1944.
- 16 Receipts etc 1944-1957.
- 17 Photographs of 1979 and 1984.
- 18 Sketch of West Mill.
- 19 1980s repair works.
- 20 Leas House earthworks.
- 21 Mill Gill earthworks.
- 22 Mill water supply plan.
- 23 Mill's water supply section.
- 24 Key to elevations.
- 25 Mill complex ground floor plan.
- 26 Mill complex first floor plan.
- 27 Mill complex second floor plan.
- 28 Mill external elevations (elevations 1 to 4).
- 29 Mill internal elevations (elevations 11 to 14).
- 30 Mill internal elevations (elevations 15 and 16).
- 31 Mill complex reflected ground floor ceiling plan.
- 32 Garage and kiln range external elevations (elevations 5, 9 and 10).
- 33 Garage internal elevations (elevations 17 to 21).
- 34 Kiln range internal elevations (elevations 22 to 26).
- 35 Barn range external elevations (elevations 6 to 8).
- 36 Mill details of frame.
- 37 Power house plan.
- 38 Poultry house plan.
- 39 Cheese press.

List of Plates


- 1 General view of Leas House survey area, looking SE (photo 4/964).
- 2 Leas House survey area, structure (Site 3a), looking N (photo 4/973).
- 3 Leas House survey area, possible kiln (Site 9), looking NE (photo 9/992).
- 4 Leas House survey area, field barn (Site 14), looking NW (photo 9/996).
- 5 Leas House survey area, 1908-10 collecting chamber and weir (Sites 8a and 8c), looking N (photo 9/998).
- 6 Leas House survey area, weir (Site 12a), looking W (photo 4/982).
- 7 Leas House survey area, interior of 1913 collecting chamber (Site 12d) (photo 4/999).
- 8 Leas House survey area, inspection pit on line of 1913 culvert (Site 12b), looking N (photo 4/980).
- 9 Leas House survey area, pond for 1913 scheme (Site 12c), looking SE (photo 4/991).
- 10 Leas House survey area, 1913 collecting chamber (Site 12d), looking E (photo 9/991).
- Leas House survey area, 1913 collecting chamber and pond (Sites 12c and 12d), looking S (photo 9/973).
- 12 Mill Gill survey area, quarry (Site 23), looking E (photo 8/759).
- 13 Mill Gill survey area, track (Site 27) to and from quarry, looking E (photo 8/761).
- 14 Mill Gill survey area, ruined structure (Site 21), looking W (photo 8/764).
- 15 Mill Gill survey area, natural channel or pond (Site 22), looking SW (photo 8/770).
- Mill Gill survey area, building east of the power house (Site 31), looking N (photo 8/815).
- 17 Mill Gill survey area, building east of the power house (Site 31) after repairs, looking NW (photo 9/005).
- Mill Gill survey area, weir and sluice (Site 29a) next to power house, looking NE (photo 6/804).
- 19 Mill Gill survey area, sluice channel (Site 29a) next to power house, looking SE (photo 6/793).
- 20 Mill Gill survey area, mill race (Site 29b), looking E (photo 8/829).
- 21 Mill Gill survey area, mill pond (Site 29c), looking W (photo 7/814).
- 22 Mill Gill survey area, mill pond and sluice (Site 29c), looking SE (photo 9/016).
- 23 Mill Gill survey area, head race (Site 29e), looking N (photo 8/758).
- Mill Gill survey area, sluice arrangement at south end of header tank (Site 29f), looking S (photo 8/753).
- 25 Mill Gill survey area, launder and sluice mechanism (Site 29h), looking SE (photo 8/757).
- 26 Mill Gill survey area, overflow from launder (Site 29g), looking N (photo 9/032).
- 27 Mill (Site 36a), south external elevation (1), looking N (photo 8/745).
- 28 Mill (Site 36a), north external elevation (3), looking S (photo 8/750).
- 29 Mill (Site 36a), west external elevation (2), looking NE (photo 5/553).
- 30 Mill (Site 36a), east external elevation (4), looking W (photo 5/540).
- 31 Mill (Site 36a), ground floor room G2, looking NE (photo 7/058).
- 32 Mill (Site 36a), east wall of ground floor room G4 (elevation 15), looking NE (photo 7/079).
- 33 Mill (Site 36a), daisy mark on south wall of ground floor room G4 (elevation 11), looking S (photo 7/087).
- Mill (Site 36a), launder sluice control on south wall (elevation 11) of first floor room 1F10, looking S (photo 7/978).
- 35 Mill (Site 36a), door in south wall (elevation 11) of first floor room 1F10, looking S (photo 7/981).
- Mill (Site 36a), graffiti on west wall of first floor room 1F11 (elevation 16), looking W (photo 7/969).
- 37 Mill (Site 36a), lathe in first floor room 1F11, looking E (photo 7/961).
- 38 Mill (Site 36a), north wall of second floor room 2F15 (elevation 13), showing stored hay-rake blanks, looking NW (photo 7/867).

- 39 Mill (Site 36a), window at east end of south wall (elevation 11) in second floor room 2F15, looking S (photo 7/887).
- 40 Mill (Site 36a), door in west wall (elevation 16) of second floor room 2F16, looking W (photo 7/889).
- 41 Mill (Site 36a), inscription 'JPA 1867' to central roof truss in second floor room 2F15, looking SW (photo 7/883).
- 42 Garage (Site 36b), west end of south external elevation (10), looking N (photo 5/567).
- 43 Garage (Site 36b), east external elevation (9), looking W (photo 5/569).
- 44 Garage (Site 36b), ground floor room G7, looking E (photo 7/089).
- 45 Garage (Site 36b), north wall of ground floor room G7 (elevation 19), looking NW (photo 7/100).
- 46 Garage (Site 36b), doorway at east end of north wall (elevation 19) of first floor room 1F12, looking N (photo 7/907).
- 47 Garage (Site 36b), south wall (elevation 21) of first floor room 1F12, looking S (photo 7/936).
- 48 Garage (Site 36b), bench structure lever etc, north wall (elevation 19) of first floor room 1F12, looking N (photo 7/916).
- 49 Kiln range (Site 36c), north external elevation (5), looking S (photo 5/544).
- Kiln range (Site 36c), rear of door in west wall (elevation 22) of ground floor room G6, looking W (photo 7/116).
- Kiln range (Site 36c), passage around kiln in ground floor room G6, looking E (photo 7/136).
- Kiln range (Site 36c), west face of kiln (elevation 26) in ground floor room G6, looking E (photo 7/127).
- Kiln range (Site 36c), perforated clay tiles stacked in ground floor room G6 (photo 7/122).
- 54 Barn range (Site 36d), south external elevation (8), looking NW (photo 5/573).
- Barn range (Site 36d), cart entrance in south external elevation (8), looking NW (photo 5/571).
- 56 Barn range (Site 36d), north external elevation (6), looking S (photo 5/547).
- 57 Mill (Site 36a), waterwheel and launder in wheelhouse (G1), looking N (photo 7/174).
- 58 Mill (Site 36a), pit wheel in ground floor room G2, looking NW (photo 7/023).
- Mill (Site 36a), north post of frame and related beams in ground floor room G2, looking W (photo 7/039).
- Garage (Site 36b), pulley with wooden casing on line shaft in first floor room 1F12, looking NE (photo 7/925).
- 61 Power house (Site 32), south external elevation, looking NE (photo 6/800).
- 62 Power house (Site 32), east external elevation, looking W (photo 8/808).
- 63 Mill Gill survey area, bolts on route of pipeline to power house (Site 30b), looking N (photo 8/776).
- Power house (Site 32), west window in south elevation, looking S (photo 8/780).
- 65 Power house (Site 32), isolator over east doorway, looking E (photo 6/758).
- Power house (Site 32), west internal elevation, looking W (photo 8/784).
- 67 Power house (Site 32), east internal elevation, looking E (photo 8/782).
- Power house (Site 32), 3-phase and neutral supply wiring to west of concrete base, looking E (photo 8/802).
- 69 Power house (Site 32), fitting to external east gable (photo 8/803).
- 70 Poultry house (Site 33), south external elevation, looking N (photo 3/722).
- 71 Poultry house (Site 33), north external elevation, looking SE (photo 3/717).
- 72 Poultry house (Site 33), doorway to central south, looking N (photo 3/724).
- 73 Poultry house (Site 33), flagged culvert of mill race, looking E (photo 8/836).
- Mill Gill survey area, structure to south of poultry house (Site 33),
- 75 Mill Gill house cheese press, looking S (photo 6/808).
- 76 Mill Gill house cheese press, press section, looking S (photo 6/811).



Reproduced from the 1:25,000 scale map by permission of Ordnance Survey® on behalf of The Controller of Her Majesty's Stationary Office, © Crown copyright 1991. All rights reserved. Licence AL100013825

PROJECT NALL ACKRICO	
WEST MILL, ASKRIGG	
TITLE	
GENERAL LOCATION	
SCALE	DATE
NTS	SEPT 2012
	FIGURE
I EDAG	4



Map base provided by YDNPA.

WEST MILL, ASKRIGG	
AREAS OF SURVEY	
SCALE NTS	SEPT 2012
EDAS	FIGURE 2






Top: original scan.
Bottom: enhanced image to show mill and launder on left hand side with church tower behind.

Source: Blake collection.


WEST MILL, ASKRIGG	
TURNER'S 1816 SKETCH	
NTS	SEPT 2012
EDAS	FIGURE 3






Source: 1839 Askrigg tithe map (WYL RD/RT 12).


WEST MILL, ASKRIGG	
1839 TITHE MAP	
NTS	SEPT 2012
EDAS	FIGURE 4



Source: Ordnance Survey 1856 6" map sheet 66 (surveyed 1854).


WEST MILL, ASKRIGG	
ORDNANCE SURVEY 1856 MAP	
SCALE NTS	SEPT 2012
EDAS	FIGURE 5






Source: Ordnance Survey 1856 6" map sheet 66 (surveyed 1854).


WEST MILL, ASKRIGG	
ORDNANCE SURVEY 1856 MAP	
SCALE NTS	SEPT 2012
EDAS	FIGURE 6






Source: Ordnance Survey 1893 25" map sheet 66/3 (surveyed 1892).

WEST MILL, ASKRIGG	
ORDNANCE SURVEY 1893 MAP	
NTS	SEPT 2012
EDAS	FIGURE 7




Conveyance of land and grant of easement from Mr Abram Scarr and one other to Mr W H Burton, 29th December 1908.
Source: Blake collection.

WEST MILL, ASKRIGG	
PLAN WITH 1908 CONVEYANCE	
SCALE NTS	SEPT 2012
EDAS	FIGURE 8







Top left: early photograph of original Mill Gill power house before 1913 expansion.


Top right: pipeline to Mill Gill power house under


construction.

Bottom: collection chamber above Mill Gill Force under construction, c.1910.

Source: Kershaw collection.


WEST MILL, ASKRIGG	
MILL GILL POWER SYSTEM	
NTS	SEPT 2012
EDAS	FIGURE 9






Source: Ordnance Survey 1912 25" map sheet 66/3 (revised 1910).

WEST MILL, ASKRIGG	
ORDNANCE SURVEY 1912 MAP	
SCALE NTS	SEPT 2012
EDAS	10




Conveyance between W H Burton and R D de Grey Vyner Esq, 29th October 1913. Source: Blake collection.


WEST MILL, ASKRIGG	
1913 CONVEYANCE	
NTS	SEPT 2012
EDAS	FIGURE 11




Conveyance of land and grant of easements from Mr Abram Scarr and one other to R C De Grey Vyner Esq, 30th October 1913. Source: Blake collection.

WEST MILL, ASKRIGG	
PLAN WITH 1913 CONVEYANCE	
SCALE NTS	SEPT 2012
EDAS	12








Top left: receipt dated Mayday 1917 to Rev F M Squibb for 677 units (less 590) of electricity. Top right: invoice dated 5th April 1922 from Garnet Tucker & Co. Ltd. for fitting dynamo.

Bottom: invoice dated 15th April 1920 from Church Bros. for electric plant.


Source: Blake collection.


WEST MILL, ASKRIGG				
RECEIPTS AND INVOICES 1917-1922				
SCALE NTS	SEPT 2012			
EDAS	figure 13			




Account dated February 1943, documenting work undertaken at Mill Gill power house. Source: Blake collection.

PROJECT WEST MILL	WEST MILL, ASKRIGG					
ACCOUNT OF	ACCOUNT OF WORK 1943					
NTS	SEPT 2012					
EDAS	14					







Top right: receipt from the National Gas & Oil Engine Co. Ltd. of Ashton-under-Lyne, dated 17th January 1944. Top left: statement from Stephens Belting Company Ltd. of Birmingham, dated 31st April 1944.

Bottom: payment to Capt. Whitehead of Thornton Rust for 'one second hand engine', dated 27th April 1944. Source: Blake collection.

WEST MILL, ASKRIGG				
RECEIPTS AND INVOICES 1944				
NTS	SEPT 2012			
EDAS	15			

	<u> </u>	Cher	ASKRIGG		The Company require carrisunless a credit account has made payable to the "	Londo	pened	Third	Party, i	or payn	ept rent.	ference	DEL to Se	nder or	Y of	Mercha	ndise
Date	In,ce No.	From or To	The Company's Office Station	Sender or Consignee	Number of Articles and	accep	Weigh	nt p	Rate		Carta	age and andry arges	Ch	otal arges s. d.		£	8. (
4)444	2	30	Readland Valle	B. Q. Winding bo.	1 Drynamo.		5	27	37/5					10 4			
5).44	1			R. Landes	3800 - Het take handles	5	18.	20	19/11				-5	18 1	1		
Glad	1518	-	By binlield	Tudot acomin 1	2 RIETY EM 200 1125			3 4	1/7				-	1.6	-		
				Batters	1		9 h.		neo	center	2	10/	14	chall	124	3//	5/
										N. 8753455717							
				7	147	100			110								14

Telegrams: "Burton Askrigg." Telephone: Bainbridge 249. ASKRIGG, YORKS, May MA H Wleery Met Bown	194-/
W. H. BURTON & SO	NS
1 of pulleto @ 33/-	296
6 month olds appropries	2-9-6 1-13-0 4 2 6

Top: LNER receipt dated May 1944 for sending a dynamo to the B A Winding Company, and 3,800 6ft rake handles and 285 4ft rake handles R Launder via West Hartlepool station.

Bottom: May 1957 sale of 18 pullets, 6 cocks etc to Mr Alderson of West Borrins.

Source: Blake collection.

WEST MILL, ASKRIGG					
RECEIPTS ETC 1944-1957					
NTS	SEPT 2012				
EDAS	16				





Top: 1979 aerial photograph of the West Mill complex and Mill Gill House. Bottom: 1984 colour print of the West Mill complex. Source: Blake collection.

WEST MILL, ASKRIGG						
PHOTOGRAPHS 1979 AND 1984						
SCALE NTS	SEPT 2012					
EDAS	17					



Electricity was made in a Corn Mill

Source: Pontefract, E & Hartley, M 1942 $\it Yorkshire Cottage$, p65.

PROJECT WEST MILL, ASKRIGG				
SKETCH OF WEST MILL				
NTS	SEPT 2012			
EDAS	18			








Top: Rebuilding leat adjacent to the power house in 1986.
Bottom: Dredging the mill pond in the 1980s.
Source: Blake collection.

WEST MILL, ASKRIGG					
1980S REPAIR WORKS					
NTS NTS	SEPT 2012				
EDAS	19				


WEST MILL, ASKRIGG	LEAS HOUSE EARTHWORKS	SEPT 2012	лине 20
PROJECT WEST N	TITLE LEAS HOUS	SCALE AS SHOWN	EDAS













CONCRETE


Survey data May-July 2011

S




PROJECT WEST MILL	WEST MILL, ASKRIGG					
KEY TO ELEVATIONS						
SCALE NTS	SEPT 2012					
EDAS	^{FIGURE} 24					








WEST MILL, ASKRIGG					
MILL COMPLEX - SECOND FLOOR PLAN					
AS SHOWN	SEPT 2012				
EDAS	27				


G2 ROOM IDENTIFIERS
Survey data May-July 2011
















WEST MILL, ASKRIGG	
MILL - INTERNAL ELEVATIONS	
AS SHOWN	SEPT 2012
EDAS	30













SEPT 2012 35






z

K


K


ш

Survey data May-July 2011




PROJECT WEST MILL, ASKRIGG		
POWER HOUSE - PLAN		
AS SHOWN	SEPT 2012	
EDAS	37	





WEST MILL, ASKRIGG		
POULTRY HOUSE - PLAN		
AS SHOWN	SEPT 2012	
EDAS	38	



WEST MILL, ASKRIGG		
CHEESE PRESS		
AS SHOWN	SEPT 2012	
EDAS	39	



Plate 1: General view of Leas House survey area, looking SE (photo 4/964).



Plate 2: Leas House survey area, structure (Site 3a), looking N (photo 4/973).



Plate 3: Leas House survey area, possible kiln (Site 9), looking NE (photo 9/992).



Plate 4: Leas House survey area, field barn (Site 14), looking NW (photo 9/996).



Plate 5: Leas House survey area, 1908-10 collecting chamber and weir (Sites 8a and 8c), looking N (photo 9/998).




Plate 6: Leas House survey area, weir (Site 12a), looking W (photo 4/982).



Plate 7: Leas House survey area, interior of 1913 collecting chamber (Site 12d) (photo 4/999).



Plate 8: Leas House survey area, inspection pit on line of 1913 culvert (Site 12b), looking N (photo 4/980).



Plate 9: Leas House survey area, pond for 1913 scheme (Site 12c), looking SE (photo 4/991).



Plate 10: Leas House survey area, 1913 collecting chamber (Site 12d), looking E (photo 9/991).



Plate 11: Leas House survey area, 1913 collecting chamber and pond (Sites 12c and 12d), looking S (photo 9/973).



Plate 12: Mill Gill survey area, quarry (Site 23), looking E (photo 8/759).



Plate 13: Mill Gill survey area, track (Site 27) to and from quarry, looking E (photo 8/761).



Plate 14: Mill Gill survey area, ruined structure (Site 21), looking W (photo 8/764).



Plate 15: Mill Gill survey area, natural channel or pond (Site 22), looking SW (photo 8/770).



Plate 16: Mill Gill survey area, building east of the power house (Site 31), looking N (photo 8/815).



Plate 17: Mill Gill survey area, building east of the power house (Site 31) after repairs, looking NW (photo 9/005).



Plate 18: Mill Gill survey area, weir and sluice (Site 29a) next to power house, looking NE (photo 6/804).



Plate 19: Mill Gill survey area, sluice channel (Site 29a) next to power house, looking SE (photo 6/793).



Plate 20: Mill Gill survey area, mill race (Site 29b), looking E (photo 8/829).



Plate 21: Mill Gill survey area, mill pond (Site 29c), looking E (photo 8/865).



Plate 22: Mill Gill survey area, mill pond and sluice (Site 29c), looking SE (photo 9/016).



Plate 23: Mill Gill survey area, head race (Site 29e), looking N (photo 8/758).



Plate 24: Mill Gill survey area, sluice arrangement at south end of header tank (Site 29f), looking S (photo 8/753).



Plate 25: Mill Gill survey area, launder and sluice mechanism (Site 29h), looking SE (photo 8/757).



Plate 26: Mill Gill survey area, overflow from launder (Site 29g), looking N (photo 9/032).



Plate 27: Mill (Site 36a), south external elevation (1), looking N (photo 8/745).




Plate 28: Mill (Site 36a), north external elevation (3), looking S (photo 8/750).



Plate 29: Mill (Site 36a), west external elevation (2), looking NE (photo 5/553).



Plate 30: Mill (Site 36a), east external elevation (4), looking W (photo 5/540).




Plate 31: Mill (Site 36a), ground floor room G2, looking NE (photo 7/058).



Plate 32: Mill (Site 36a), east wall of ground floor room G4 (elevation 15), looking NE (photo 7/079).



Plate 33: Mill (Site 36a), daisy mark on south wall of ground floor room G4 (elevation 11), looking S (photo 7/087).




Plate 34: Mill (Site 36a), launder sluice control on south wall (elevation 11) of first floor room 1F10, looking S (photo 7/978).



Plate 35: Mill (Site 36a), door in south wall (elevation 11) of first floor room 1F10, looking S (photo 7/981).




Plate 36: Mill (Site 36a), graffiti on west wall of first floor room 1F11 (elevation 16), looking W (photo 7/969).



Plate 37: Mill (Site 36a), lathe in first floor room 1F11, looking E (photo 7/961).



Plate 38: Mill (Site 36a), north wall of second floor room 2F15 (elevation 13), showing stored hay-rake blanks, looking NW (photo 7/867).



Plate 39: Mill (Site 36a), window at east end of south wall (elevation 11) in second floor room 2F15, looking S (photo 7/887).



Plate 40: Mill (Site 36a), door in west wall (elevation 16) of second floor room 2F16, looking W (photo 7/889).



Plate 41: Mill (Site 36a), inscription 'JPA 1867' to central roof truss in second floor room 2F15, looking SW (photo 7/883).




Plate 42: Garage (Site 36b), west end of south external elevation (10), looking N (photo 5/567).




Plate 43: Garage (Site 36b), east external elevation (9), looking W (photo 5/569).



Plate 44: Garage (Site 36b), ground floor room G7, looking E (photo 7/089).



Plate 45: Garage (Site 36b), north wall of ground floor room G7 (elevation 19), looking NW (photo 7/100).



Plate 46: Garage (Site 36b), doorway at east end of north wall (elevation 19) of first floor room 1F12, looking N (photo 7/907).




Plate 47: Garage (Site 36b), south wall (elevation 21) of first floor room 1F12, looking S (photo 7/936).



Plate 48: Garage (Site 36b), bench structure lever etc, north wall (elevation 19) of first floor room 1F12, looking N (photo 7/916).



Plate 49: Kiln range (Site 36c), north external elevation (5), looking S (photo 5/544).



Plate 50: Kiln range (Site 36c), rear of door in west wall (elevation 22) of ground floor room G6, looking W (photo 7/116).



Plate 51: Kiln range (Site 36c), passage around kiln in ground floor room G6, looking E (photo 7/136).



Plate 52: Kiln range (Site 36c), west face of kiln (elevation 26) in ground floor room G6, looking E (photo 7/127).



Plate 53: Kiln range (Site 36c), perforated clay tiles stacked in ground floor room G6 (photo 7/122).



Plate 54: Barn range (Site 36d), south external elevation (8), looking NW (photo 5/573).



Plate 55: Barn range (Site 36d), cart entrance in south external elevation (8), looking NW (photo 5/571).



Plate 56: Barn range (Site 36d), north external elevation (6), looking S (photo 5/547).



Plate 57: Mill (Site 36a), waterwheel and launder in wheelhouse (G1), looking N (photo 7/174).



Plate 58: Mill (Site 36a), pit wheel in ground floor room G2, looking NW (photo 7/023).



Plate 59: Mill (Site 36a), north post of frame and related beams in ground floor room G2, looking W (photo 7/039).



Plate 60: Garage (Site 36b), pulley with wooden casing on line shaft in first floor room 1F12, looking NE (photo 7/925).




Plate 61: Power house (Site 32), south external elevation, looking NE (photo 6/800).




Plate 62: Power house (Site 32), east external elevation, looking W (photo 8/808).




Plate 63: Mill Gill survey area, bolts on route of pipeline to power house (Site 30b), looking N (photo 8/776).



Plate 64: Power house (Site 32), west window in south elevation, looking S (photo 8/780).



Plate 65: Power house (Site 32), isolator over east doorway, looking E (photo 6/758).



Plate 66: Power house (Site 32), west internal elevation, looking W (photo 8/784).



Plate 67: Power house (Site 32), east internal elevation, looking E (photo 8/782).



Plate 68: Power house (Site 32), 3-phase and neutral supply wiring to west of concrete base, looking E (photo 8/802).



Plate 69: Power house (Site 32), fitting to external east gable (photo 8/803).




Plate 70: Poultry house (Site 33), south external elevation, looking N (photo 3/722).



Plate 71: Poultry house (Site 33), north external elevation, looking SE (photo 3/717).



Plate 72: Poultry house (Site 33), doorway to central south, looking N (photo 3/724).



Plate 73: Poultry house (Site 33), flagged culvert of mill race, looking E (photo 8/836).



Plate 74: Mill Gill survey area, structure to south of poultry house (Site 33),



Plate 75: Mill Gill house cheese press, looking S (photo 6/808).



Plate 76: Mill Gill house cheese press, press section, looking S (photo 6/811).