

Plate 32: General view of C1 (film 12.8)



Plate 33: General view of C3 (film 12.7)




Plate 34: General view of C1 (film 12.10)



Plate 35: Detail of machine base in C3 (film 12.3)




Plate 36: General view into C2, boiler room (film 12.1)



Plate 37: Detail of piping within southwest wall of C2 (film 13.25)



Archaeological Building Recording, Loughborough Technical College, Greenclose Lane, Loughborough, Leicestershire ARCUS 1199.1(1) – 2008




Plate 39: View of stairway, from ground floor (film 13.21)



Plate 40: General view of windows on mezzanine floor overlooking G5 (film 13.19)





Archaeological Building Recording, Loughborough Technical College, Greenclose Lane, Loughborough, Leicestershire ARCUS 1199.1(1) – 2008