

11 PLATES



Plate 1 - Pond A prior to de-silting



Plate 2 - Section of Pond A with showing basal clay



Plate 3 - Pond A southern end



Plate 4 – Deposit [102] running under the bank deposit



Plate 5 - Pond A after de-silting



Plate 6 - Culvert [107]



Plate 7 - Pond B after de-silting



Plate 8 - Rubble deposit [106] in Pond B



Plate 9 - Silt stockpile in lower southwest corner of field