

Woodlands Farm, Front Street, Treeton, Rotherham

Archaeological Building Recording

Contents

List of Illustrations. Illustrations not in the body of the text
are to be found at the rear of the report

1. Introduction
 2. Methodology
 3. Historical Data
 4. Description of the Roof Structures
 5. Conclusion
 6. Acknowledgements
- Appendix 1: Rotherham MBC Brief
- Appendix 2: Photographic Register

Summary

In advance of development the roof claddings had been removed from two farm buildings at Treeton, The smaller of the two had a three-bay roof of oak and dated to the mid 18th century. Many of the timbers had been reused and some showed evidence of timber framing. The larger building was a range of three wings of six, seven and nine bays. The roof was constructed of soft-wood with two hipped corners and dated from the mid 19th century. The roof timbers were photographically recorded.

Authorised for distribution by:

.....

ISOQAR ISO 9001:2000
Cert. No. 125/93
© WYAS
Archaeological Services WYAS
PO Box 30, Nepshaw Lane South, Morley, Leeds LS27 0UG

List of Figures

- Figure 1. General Location Map
- Figure 2. Detailed Location Map
- Figure 3. Ordnance Survey, sheet 295 NE, published 1900
- Figure 4. Ordnance Survey, sheet 295 NE, published 1904
- Figure 5. Ordnance Survey, sheet 295 NE, published 1923