

SITE ADDRESS	Utility trench, Highcliffe Court, adj.110 Clifton, York				
CLIENT NAME	CE Electric UK				
YAT PROJECT#	5470 YAT REPORT # 2011/1				
MUSEUM ACCESSION #	n/a GRID REFERENCE SE 5942 5295				
PLANNING REFERENCE #	n/a AAI OPS NOTICE # 10032				

INTRODUCTION

On 6th January 2011 York Archaeological Trust undertook a watching brief at the south-west end of Highcliffe Court, Clifton, York (Figure 1). The objective was to record any archaeological remains exposed during the excavations for a new electricity supply to a telephone cabinet in the pavement adjacent to 110 Clifton (Figures 2 and 3). The excavation was not observed but the site was visited at a point when the main part of the trench was open. Recording was by means of written notes and measured sketches supplemented by a number of colour digital photographs.




Figure 1 Site location (highlighted)

COMPLI	COMPLETED BY D.T. Evans		CHECKED BY	M.R. Stockwell		FINISHED	18/03/11	
FINDS	No	•	SAMPLES	No	PHOTOS	Yes	PAGE	1 of 4





SITE ADDRESS	Utility trench, Highcliffe Court, adj.110 Clifton, York					
CLIENT NAME	CE Electric UK					
YAT PROJECT#	5470 YAT REPORT # 2011/1					
MUSEUM ACCESSION #	n/a	GRID REFERENCE	SE 5942 5295			
PLANNING REFERENCE #	n/a	AAI OPS NOTICE #	10032			




Figure 2 Location of works

RESULTS

A single specimen section was recorded towards the north-east end of the trench. Here, between 0.35m below ground level (BGL) and at least the base of the trench at 0.6m BGL, there was a firm mid brown clay (1000). This was overlain by a 0.2m deep layer of mid brown silt with moderate pale brown mortar and brick / tile (1001). Sealing this was a 0.1m deep deposit of pale grey crushed limestone (1002) which formed the make-up for the existing pavement surface of tarmac (1003).

COMPL	PLETED BY D.T. Evans		CHECKED BY	M.R. Stockwell		FINISHED	18/03/11
FINDS	No	SAMPLES	No	PHOTOS	Yes	PAGE	2 of 4



SITE ADDRESS	Utility trench, Highcliffe Court, adj.110 Clifton, York					
CLIENT NAME	CE Electric UK					
YAT PROJECT#	5470 YAT REPORT # 2011/1					
MUSEUM ACCESSION #	n/a	GRID REFERENCE SE 5942 529				
PLANNING REFERENCE #	n/a	AAI OPS NOTICE # 10032				




Figure 3 Location of trench and recorded section

CONCLUSIONS

Although relatively close to the modern ground surface the firm, mid brown clay (1000) seen towards the base of the trench was probably natural. No features were seen to be cut through and none of the overying layers were deemed to be of any great age or archaeological significance and were probably or definitely modern.

COMPL	ETED BY D.T. Evans		CHECKED BY	M.R. Stockwell		FINISHED	18/03/11
FINDS	No	SAMPLES	No	PHOTOS	Yes	PAGE	3 of 4





SITE ADDRESS	Utility trench, Highcliffe Court, adj.110 Clifton, York					
CLIENT NAME	CE Electric UK					
YAT PROJECT#	5470 YAT REPORT # 2011/1					
MUSEUM ACCESSION #	n/a	GRID REFERENCE	SE 5942 5295			
PLANNING REFERENCE #	n/a	AAI OPS NOTICE #	10032			



Plate 1 North-east end of trench, looking north-east



Plate 2 General view of works, looking north-east

COMPLI	D.T. Evans		CHECKED BY	M.R. Stockwell		FINISHED	18/03/11	
FINDS	No		SAMPLES	No	PHOTOS	Yes	PAGE	4 of 4

