

SITE	Wall to the rear of 10 Precentor's Court Interim Report				
CLIENT NAME	CYC				
YAT PROJECT #	6081	2018/68			
MUSEUM ACCESSION #	N/A	GRID REFERENCE	SE 60160 52254		
PLANNING REFERENCE #	N/A	AAI OPS NOTICE#	N/A		

INTRODUCTION

A watching brief was undertaken by York Archaeological Trust on behalf of CYC on the 24th July 2018 to the rear of 10 Precentor's Court, York, NGR SE 60160 52254 (Figure 1). The objective of the watching brief was to record the rear wall structure and any archaeological deposits exposed by the ground works.

METHODOLOGY

A square 0.5m x 0.5m trial pit was hand excavated by the City of York's Ancient Monument team, adjacent to the rear boundary wall, to a depth of 0.84m below ground level. Notes and a measured sketch of the wall were taken, and digital photographs were taken of the wall elevation and of the pit post excavation

RESULTS

Below ground level, the wall comprised of large limestone blocks, squared and in a random course. The stones measured between $0.21 \text{m} \times 0.15 \text{m}$ and $0.24 \text{m} \times 0.21 \text{m}$. A single brick was seen within the wall at the base of the trial pit, measuring $0.15 \text{m} \times 0.10 \text{m}$ in dimension. The bonding material of the wall was hard to determine as the mortar had recessed or been raked out. Above ground level the rear wall had been rebuilt and strengthened, evidenced by the presence of brickwork and concrete mortar.

The excavated soft ground deposit comprised of loose dark grey brown sandy silt, which contained numerous roots and occasional small fragments of brick.

CONCLUSION

The date of the wall is unclear; however it is clearly shown on the 1852 OS map of York and it is likely that it dates to at least the construction of 10 Precentor's Court in the 18th century. Nothing of archaeological interest was retrieved from the test pit.

A recording survey will be conducted on the whole wall in the future.

COMPLETED BY C		Jackson	CHECKED BY	M. S	later	FINISHED	26/09/19	
FINDS	0		SAMPLES	0	PHOTOS	2	PAGE	1 of 5









SITE	Wall to the rear of 10 Precentor's Court Interim Report				
CLIENT NAME	CYC				
YAT PROJECT #	6081 YAT REPORT # 2018/68				
MUSEUM ACCESSION #	N/A	GRID REFERENCE	SE 60160 52254		
PLANNING REFERENCE #	N/A	AAI OPS NOTICE #	N/A		




Figure 1 Site Location

Crown copyright reserved. Reproduced with the permission of OS on behalf of HMSO. Licence number 100018343

COM	COMPLETED BY C Jackson		CHECKED BY	M. Slater		FINISHED	26/09/19	
FIND	0		SAMPLES	0	PHOTOS	2	PAGE	2 of 5





Registered Office: 47 Aldwark, York YO1 7BX Tel: 01904 663000 Fax: 01904 663024



A Company Limited by Guarantee Without Share Capital Registered in England No. 1430801



SITE	Wall to the rear of 10 Precentor's Court Interim Report				
CLIENT NAME	CYC				
YAT PROJECT #	6081 YAT REPORT # 2018/6				
MUSEUM ACCESSION #	N/A	GRID REFERENCE	SE 60160 52254		
PLANNING REFERENCE #	N/A	AAI OPS NOTICE #	N/A		




Figure 2 Wall elevation

COMPLETED BY C		Jackson	CHECKED BY	M. Slater		FINISHED	26/09/19	
FINDS	0		SAMPLES	0	PHOTOS	2	PAGE	3 of 5







SITE	Wall to the rear of 10 Precentor's Court Interim Report				
CLIENT NAME	CYC				
YAT PROJECT #	6081 YAT REPORT # 2018				
MUSEUM ACCESSION #	N/A	GRID REFERENCE	SE 60160 52254		
PLANNING REFERENCE #	N/A	AAI OPS NOTICE #	N/A		



Plate 1, view of southwest facing wall

COMPLETED BY C.		Jackson	CHECKED BY	M. S	later	FINISHED	26/09/19	
FINDS	0		SAMPLES	0	PHOTOS	2	PAGE	4 of 5

Registered Charity in England & Wales (509060) & Scotland (SCO42846)



Registered Office: 47 Aldwark, York YO1 7BX Tel: 01904 663000 Fax: 01904 663024



A Company Limited by Guarantee Without Share Capital Registered in England No. 1430801



SITE	Wall to the rear of 10 Precentor's Court Interim Report				
CLIENT NAME	CYC				
YAT PROJECT #	6081 YAT REPORT # 2018				
MUSEUM ACCESSION #	N/A	GRID REFERENCE	SE 60160 52254		
PLANNING REFERENCE #	N/A	AAI OPS NOTICE #	N/A		



Plate 2 view northeast of later additions to the wall.

This Report has been prepared solely for the person/party which commissioned it and for the specifically titled project or named part thereof referred to in the Report. The Report should not be relied upon or used for any other project by the commissioning person/party without first obtaining independent verification as to its suitability for such other project, and obtaining the prior written approval of York Archaeological Trust for Excavation & Research Limited ("YAT"). YAT accepts no responsibility or liability for the consequences of this Report being relied upon or used for any purpose other than the purpose for which it was specifically commissioned. Nobody is entitled to rely upon this Report other than the person/party which commissioned it. YAT accepts no responsibility or liability for any use of or reliance upon this Report by anybody other than the commissioning person/party.

COMPL	COMPLETED BY C Jackson		Jackson	CHECKED BY	M. S	later	FINISHED	26/09/19
FINDS	0		SAMPLES	0	PHOTOS	2	PAGE	5 of 5

Registered Charity in England & Wales (509060) & Scotland (SCO42846)



Registered Office: 47 Aldwark, York YO1 7BX Tel: 01904 663000 Fax: 01904 663024



A Company Limited by Guarantee Without Share Capital Registered in England No. 1430801